


NTS 02-G & NTS 03-G+ Firmware Release Notes

VERSION 3.21r7 (May 2018)

- **Feature:** A new feature, **NTP on PRP** has been introduced in this firmware version. This allows NTP to function with PRP. Previously the NTP was disabled when PRP was activated.
- **Bug:** When the clock was synchronizing to PTP, the clock would use the leap second value if the UTC valid flag was not set. This behaviour has been corrected, and the clock will only take the leap second value if the UTC valid flag is set. If the flag is not set the clock will ignore the incoming value and continue to use any previously set value.

VERSION 3.21r6 (March 2018)

- **Feature:** PTP C37.238-2017 and 61850-9-3 Power Utility profile has been added. ConfigTool v4.3.1.5 or later is required to select this Profile.



- **Improvement:** While configuring NTP multicast address, if the IPv4 address assigned for multicast is an invalid address, then the clock will use the broadcast MAC address. For valid IPv4 multicast addresses a valid multicast MAC will still be used.
- **Improvement:** Clocks getting their Sync from IRIG-B or PTP will advertise Stratum-1. Previously they were advertised as Stratum-2
- **Improvement:** Added ability to lockout a user for a period following several unsuccessful login attempts. Both the number of unsuccessful attempts and the period of lockout can be configured.

System Policy

Login attempts before lockout

Lockout Period Seconds

Minimum password length

Password must contain n groups* of 4

Don't allow username in password

Two passwords

* of Upper Case, Lower Case, numeric & control

By default, this feature is disabled (Logging attempts before lockout set to 0) and this will be the case for clocks upgraded to this version.

To prevent the leaking of security information there is no notification to a user that the lockout is in place, and the standard login failed message will be displayed.

The lockout is based on the user account and operates regardless of the IP address that the attempt is made from or if the attempt is made via SNMP or the Config Tool. Similarly, a failed login via any method or from any address adds to the users failed login attempts count.

The lockout is per account and a lockout on one account does not prevent other accounts from logging in.

Subsequent incorrect login attempts during the lockout period will not increase that period. SNMPv3 traps authenticated with the credentials of a locked-out user will still be sent.

Config Tool 4.3.1.0 Is required to access this feature.

- **Improvement:** Modified NTP broadcast and multicast periods to be expressed in raw seconds, rather than powers of two. This will allow a wider range of options than previously available but excludes rates of more than one message per second.

When upgrading the intervals will automatically be converted from the earlier format and any intervals of less than one second will be rounded up to one second.

ConfigToolIII 4.3.1.1 is required to select or view the full range of intervals.

Send broadcast every Hours Minutes Seconds

Send multicast every Hours Minutes Seconds

Figure 1 NTP Broadcast/Multicast Rate Selection in ConfigToolIII 4.3.1.1 and later.

Config Tools earlier than 4.3.1.1 offer a fixed set of options and will map the interval to one of the these as follows:

Old Value	New Value	Old Value	New Value
1/8 th Second	1 Second	128 Seconds	2 Minutes
1/4 th Second	1 Second	256 Seconds	5 Minutes
½ Second	1 Second	512 Seconds	10 Minutes
1 Second	1 Second	1024 Seconds	15 Minutes

because timing is everything

2 Seconds	2 Seconds		2048 Seconds	30 Minutes
4 Seconds	5 Seconds		4096 Seconds	1 Hour
8 Seconds	10 Seconds		8192 Seconds	2 Hours
16 Seconds	15 Seconds		16384 Seconds	5 Hours
32 Seconds	30 Seconds		32768 Seconds	10 Hours
64 Seconds	1 Minute			

The NTP client request rate is not modified by this change.

There is a new MIB (201801250000Z) which includes the new objects

- tncNTPBroadcastInterval
- tncNTPMulticastInterval

- **Bug Fix:** With Soft PRP bug was discovered were if one Ethernet connection was removed the Soft PRP link was lost.
- **Bug Fix:** A bug in the PTP BMCA algorithm was discovered where the PTP Slave clock would go into an Uncalibrated State if the Best Master changed frequently in the network.
- **Bug Fix:** Front panel display now indicates 'LDT' when daylight savings is in effect and the local time is being displayed. Previously, 'LST' was shown regardless of daylight savings settings.



VERSION 3.21r3 (November 2017)

- **Improvement:** Added a “maximum inaccuracy check” option, which allows a time inaccuracy threshold to be set, at which the clock will leave holdover and indicate out of sync. This option can be used instead of, or in addition to, the “holdover timeout” option, which causes the clock to indicate out of sync after a specified time in holdover.

The “maximum inaccuracy check” option is useful for ensuring that the clock does not exceed a specific accuracy level. The clock will automatically take into account factors such as the fitted frequency reference and time in sync to determine how long to remain in holdover.

If both “holdover timeout” and “maximum inaccuracy check” are enabled, the clock will leave holdover and indicate out of sync only when both the holdover time has expired, and the inaccuracy threshold has been crossed.

- **Improvement:** Added the ability to independently suppress individual outputs based on inaccuracy threshold or holdover timeout. When “holdover timeout expires” is selected, that particular output will stop providing a time signal when the clock is out of sync and the specified holdover time has expired.

When “Inaccuracy threshold is exceeded” is selected, that particular output will stop providing a time signal when the clock is out of sync and the reported inaccuracy has exceeded the specified maximum inaccuracy. When “Never” is selected, that particular output will continue to provide a time signal even when the clock is out of sync.

This applies to the following ports:

- P3 configurable IRIG-B / Pulse output port
- P6, P7, P8, P9, P10, P11 configurable IRIG-B / Pulse output ports

- **Change:** The persistent holdover availability option is now no longer optional, and is permanently enabled. This is required for correct operation of the clock with the added “maximum inaccuracy check” option.

VERSION 3.21r2 (October 2017)

- **Bug Fix:** Fixed a bug where the leap second pending and daylight saving pending bits in IRIG-B C37.118.1 outputs, and the leap indicator in NTP responses, were cleared one second late. This bug was introduced in version 3.21r.

VERSION 3.21r1 (October 2017)

- **Improvement:** Added the ability to apply firmware upgrades to the GNSS receiver module of NTS 03-G+ clocks fitted with OCXO or Rubidium oscillators. This change allows for future field

because timing is everything

upgrades to be applied to the GNSS receiver module. Clocks not fitted with OCXO or Rubidium oscillators already have this capability.

- **Bug Fix:** Fixed a bug introduced in version 3.21r that prevented the “GPS Reset” command from having any effect on NTS 03-G+ units fitted with OCXO or Rubidium oscillators.

VERSION 3.21r (May 2017)

- **Improvement:** The “Reset GPS” or “Reset GNSS” command sent from the Tekron Configuration Tool will now perform a factory reset of the clock’s integrated GNSS receiver. This will reset all configuration parameters stored in the memory of the GNSS receiver. Note that this does not change any configuration settings applied by the Tekron Configuration Tool. Previously, a “cold” reset of the GNSS receiver was performed, which did not clear all parameters.
- **Improvement:** The time quality reported by the SNTP client time source for the purpose of source selection is now limited to be no better than 1 μ s. This is to prevent the SNTP source from being selected when a high-quality GPS or PTP source is available.
- **Improvement:** The time quality comparison performed by the clock to select between multiple available time sources now uses “banding”. The time quality reported by each available source is rounded to the nearest 100ns “band”, before it is compared to other sources. This helps to prevent unnecessary frequent switching between two sources of similar quality.
- **Improvement:** The failure to obtain an IPv4 address via DHCP will result in the clock adopting an ARP tested Link-Local address (169.254.xxx.xxx). An IPv4 address fail alarm will now be displayed both in the Configuration Tool and on the LCD display. When this alarm occurs, the user may need to update their network adaptor settings to a Link-Local address to gain access to the clock. The alarm will persist until the IPv4 address settings are changed or the clock is connected to a DHCP enabled network.

The alarm appears in the Configuration Tool as “ipv4 address”, and on the display as “IPe1”, or “IPe2”. “IPe1” and “IPe2” stand for “IP error, port ETH1” and “IP error, port ETH2” respectively. This alarm does not open any alarm relays, and does not send an SNMP notification.



- **Change:** Updated the default new clock UTC-TAI offset to be 37 seconds as per the leap second added on January 1st, 2017.
- **Bug Fix:** During the recent (December 2016) leap second event, it was observed that the GNSS/GPS receiver module continued to report the previous UTC-TAI offset for many hours following the actual changeover. Prior to 3.21r, the firmware would ignore the UTC offset advice from the GNSS/GPS module for six and a quarter hours following the leap second event. This was found to be insufficient, and has been increased to 36 hours.

- **Bug Fix:** Fixed a bug that, if the 'Suppressed when out of sync' option is selected, caused the first pulse of the first IRIG-B frame to occur 2 milliseconds early when sync is achieved.
- **Bug Fix:** Fixed a bug introduced in version 3.18r that could, in rare conditions, cause an Ethernet port configured with a fixed IP address to unexpectedly revert to a link local (169.254.xxx.xxx) IP address.
- **Bug Fix:** Fixed a bug that could, in rare conditions, cause PTP timestamps to be miscalculated.
- **Bug Fix:** The "Block VLAN 0" advanced configuration option can now be set on non-admin ports with the Configuration Tool connected to the admin port. Previously, this configuration option was not accessible on non-admin ports while connected to the admin port.

VERSION 3.20r2 (April 2017)


- **Change:** This firmware allows for the NTS 03-G+ to use either the NTS 03-G or NTS 03-G+ branding. This is a factory configurable option only.

VERSION 3.20r1 (January 2017)

- **Feature:** Added support for enabling the persistent holdover availability option. Tekron Configuration Tool 4.2.1.10 or later is required to enable this option.

Normally, the clock can only enter holdover if it has been in sync for at least 5 minutes. If persistent holdover is enabled, and the clock has initially been in sync for at least 5 minutes, then the clock can still enter holdover if it experiences a sync switching condition. For example, sync is lost, regained for less than 5 minutes, then lost again. Such a condition may exist when GNSS jamming is present, or in the case of a poor antenna installation.

Please note, when entering holdover after a period of intermittent sync the holdover period timer is reset. This may cause the clock to enter into an extended holdover period, if the sync switching condition continues to be present. By disabling persistent holdover, you can ensure that the time in holdover is not extended by periods of intermittent sync lasting less than 5



minutes.

- **Bug Fix:** Fixed a bug that, in a rare event, could cause the clock to output a time exactly 2 seconds behind the correct time. This bug was most likely to affect NTS 03-G+ units fitted with the OCXO or Rubidium frequency reference option.
- **Bug Fix:** Fixed a bug that could cause the Configuration Tool to unexpectedly lose the connection to the clock when running on a PC that is singly attached to a PRP network (connected to only one of the two PRP redundant networks).

VERSION 3.20r (November 2016)

- **Feature:** Added support for NTS 03-G+ 4 Port Plus IRIG-B Expansion. Tekron Configuration Tool 4.2.1.0 or later is required to configure the 4 Port Plus IRIG-B Expansion programmable outputs.
- **Feature:** Added support for NTS 03-G+ OCXO and Rubidium frequency reference options.
- **Feature:** Added support for Parallel Redundancy Protocol (PRP). Ports ETH3 and ETH4 (and ETH5 and ETH6 where fitted), can be linked to form a redundant pair. PRP support is available on all existing NTS 02-G and NTS 03-G hardware. Tekron Configuration Tool 4.2.1.0 or later and a PRP license are required to enable PRP support. Please contact Tekron to purchase a PRP license.
- **Feature:** Added support for ITU-T G.8275.1 PTP Telecom Profile. Both Telecom Grandmaster and Slave operation is supported. Tekron Configuration Tool 4.1.1.0 or later is required to configure PTP in this profile.
- **Feature:** Added an option to allow the unit to be reset to factory defaults in the event of a forgotten administrator password. Physical access to the unit is required to perform the reset procedure. This option is disabled by default. Tekron Configuration Tool 4.2.1.0 or later is required to enable this option. When this option is disabled, the unit must be returned to Tekron for reprogramming in the event of a forgotten administrator password. This option may be permanently disabled by Tekron on request. This factory reset is different from the factory reset that can be performed with the Configuration Tool, as that reset does not require physical access, but requires an administrator password.
- **Improvement:** Added ability to disable the holdover time setting, allowing the clock to remain in holdover indefinitely. This leaves it up to client devices to determine when they will stop synchronizing to the clock, based on the advertised quality in the time outputs.
- **Improvement:** Added a configurable option for suppression of output signals at startup, when the clock has not yet received a valid time.
- **Improvement:** Added a Fixed Manual delay mode to the available PTP delay mechanisms, in addition to the existing End-to-End and Peer-to-Peer options. Fixed Manual delay mode may be useful in some non PTP aware networks (networks which do not have switches with PTP support).

- **Improvement:** Added a PTP Forced Master option. When selected, this option ensures that the port will not operate as a PTP Slave.
- **Bug Fix:** Fixed a bug that could cause loss of communication to non-admin Ethernet ports after 25 days of operation. If this event occurs, non-admin Ethernet ports (ETH2 and above) will stop acting as an NTP or PTP master. Resetting the clock will restore normal operation.
- **Bug Fix:** Fixed a bug that could cause PTP Announce messages generated by the unit to occasionally contain incorrect information when the unit is itself synchronized to an external PTP grandmaster, that is, when the unit is operating as a PTP boundary clock.

VERSION 3.18r6 (October 2016)

- **Bug Fix:** The NTP time stamp consists of two fields, a 32 bit field for the number of seconds since 1 January 1900 and a 32 bit field for the sub-second fraction. From 23:00:00 UTC on December 31st 2016 (one hour before the leap second is applied) the sub-second fraction will be frozen at its maximum value (binary all 1's). However, the number of seconds field will continue to update and maintain correct time. This has the effect of decreasing the time stamp resolution from 16ns to 1s and means that the date and time will remain accurate down to 1 second accuracy only. At 23:59:00 UTC the sub-second fraction will return to normal operation and the leap second will be applied correctly.
- **Bug Fix:** Added the ability to automatically recover from an internal communication error. This rare event could cause non-admin Ethernet ports (ETH2 and above) to unexpectedly lose synchronization. Resetting the unit will return it to normal operation.

VERSION 3.18r5 (Limited Release)

- **Feature:** Fiber Slave option introduced.

VERSION 3.18r4 (March 2016)

- **Initial Release**