

## TCG 01-G & TCG 02-G Ethernet Release Notes

### VERSION 3.21r1 (October 2017)

- **Improvement:**  
Added the ability to apply firmware upgrades to the GNSS receiver module of TCG 02-G clocks fitted with OCXO or Rubidium oscillators. This change allows for future field upgrades to be applied to the GNSS receiver module to add features or resolve issues. Clocks not fitted with OCXO or Rubidium oscillators already have this capability.

### VERSION 3.21r (May 2017)

- **Feature:**  
Added an advanced configuration option to use local time instead of UTC time for NTP timestamps. This is non-standard, but may be required in certain applications. This option applies to both server and client operation, and is set independently on each port. Tekron Configuration Tool 4.2.1.10 or later is required to enable this option.
- **Feature:**  
Added an option to allow the unit to be reset to factory defaults in the event of a forgotten administrator password. Physical access to the unit is required to perform the reset procedure. Please refer to the Tekron website for the reset procedure. This option is disabled by default. Tekron Configuration Tool 4.2.1.0 or later is required to enable this option.

When this option is disabled, the unit must be returned to Tekron for reprogramming in the event of a forgotten administrator password.

- **Improvement:**  
The failure to obtain an IPv4 address via DHCP will result in the clock adopting an ARP tested Link-Local address (169.254.xxx.xxx). An IPv4 address fail alarm will now be displayed both in the Configuration Tool and on the LCD display. When this alarm occurs, the user may need to update their network adaptor settings to a Link-Local address to gain access to the clock. The alarm will persist until the IPv4 address settings are changed or the clock is connected to a DHCP enabled network.

The alarm appears in the Configuration Tool as “ipv4 address”, and on the display as “IPe1”, or “IPe2”. “IPe1” and “IPe2” stand for “IP error, port ETH1” and “IP error, port ETH2” respectively. This alarm does not open any alarm relays, and does not send an SNMP notification.



- **Bug Fix:**  
Fixed a bug that would cause the Fill Pattern transmitted to revert to None after about 1 second, when “All Zeros” fill pattern is selected for the P15 or P16 T1/E1 outputs on a TCG 02-G fitted with M3 (Telecom) expansion.

## VERSION 3.20r (Not Released for TCG 01-G & TCG 02-G)

## VERSION 3.19r (10 August 2016)

- **New feature:**  
Added support for ITU-T G.8275.1 PTP Telecom Profile. Both Telecom Grandmaster and Slave operation is supported. Tekron Configuration Tool 4.1.1.0 or later is required to configure PTP in this profile.
- **Improvement:**  
PTP slave algorithm has been improved to be more resistant to noise and transients in the PTP time source, which could be caused by heavy or varying network traffic, or by network reconfiguration.
- **Improvement:**  
Additional checks are now performed on incoming PTP messages when operating as a PTP slave, in order to improve resistance against possible PTP spoofing attempts.

## VERSION 3.18 (Not Released for TCG 01-G & TCG 02-G)

## VERSION 3.17 (Not Released)

## VERSION 3.16 (Not Released for TCG 01-G & TCG 02-G)

## VERSION 3.15 (Not Released for TCG 01-G & TCG 02-G)

## VERSION 3.14r5 (16 March 2016)

- **Bug Fix:**  
When the GNSS satellite constellation is restricted to GLONASS only, and it has not been previously synchronised to GPS, the UTC time may be offset by the current leap second difference between GPS and UTC time. This fix detects and corrects the offset.

## VERSION 3.14r4 (Limited Release)

## VERSION 3.14r3 (Not Released for TCG 01-G & TCG 02-G)

## VERSION 3.14r2 (Not Released for TCG 01-G & TCG 02-G)

## VERSION 3.14r (29 July 2015)

- **Improvement:**  
Ethernet auto-negotiation timeout periods have been increased from a few milliseconds to 1 second to improve interoperability with some network infrastructure equipment.
- **Bug Fix:**  
Clock will now accept notification of an upcoming leap second from NTP or PTP when operating as an NTP client or PTP slave. This fault caused the leap second to happen late.

## VERSION 3.13r2 (Limited Release)

- **Improvement:**  
Additional support added for OCXO and Rubidium oscillators (TCG 02-G only).

## VERSION 3.13r (Limited Release)

- **Improvement:**  
Support added for clocks fitted with OCXO and Rubidium oscillators (TCG 02-G only).
- **Improvement:**  
Support added for longer holdover times, to allow for the increased stability of the OCXO and Rubidium oscillators to be fully utilized.
- **Improvement:**  
Ethernet module now follows the sync status of the host TCG. Previously, the Ethernet module determined the sync status of the clock by interpreting GPS data, which could result in the NTP, PTP and SNMP sync status and quality information differing from that of the other outputs.
- **Improvement:**  
When active, test mode will now override any other active time sources. This improves the ease of use of test mode, as it is no longer necessary to ensure that all other time sources are disabled.
- **Improvement:**  
Increased rate of GPS leap second information requests. Previously, GPS leap second information requests would only be made 1 minute prior to, or 6 hours following an already scheduled leap second event. GPS leap second information requests are now made every 12.5 minutes following first almanac.
- **Improvement:**  
Added the ability to select None as the delay calculation method for PTP. This allows a fixed delay to be used instead of a calculated delay.
- **Improvement:**  
Added Mobile GPS mode, which allows for the GPS Clock to be installed on board a slow-moving vehicle or vessel. This mode is considered experimental.

- **Improvement:**

During the leap second the sub second fraction of the NTP time stamp is now held at one count before the end of the second (for the entire second). Previously the sub-second fraction rolled to zero at the start of the leap second and counted up as per a normal second. Because most leap seconds are a repetition of the last second of the day, if the sub second fraction is not held at one count before the end of the second, timestamps taken during the leap second could appear to be earlier in time than stamps recorded during the previous second.

Old Leap Second Behavior	New Leap Second Behavior
23:59:58.00	23:59:58.00
23:59:58.25	23:59:58.25
23:59:58.50	23:59:58.50
23:59:58.75	23:59:58.75
23:59:59.00	23:59:59.00
23:59:59.25	23:59:59.25
23:59:59.50	23:59:59.50
<b>23:59:59.75</b>	<b>23:59:59.75</b>
<b>23:59:59.00</b>	<b>23:59:59.99</b>
23:59:59.25	23:59:59.99
23:59:59.50	23:59:59.99
23:59:59.75	23:59:59.99
00:00:00.00	00:00:00.00
00:00:00.25	00:00:00.25

- **Bug Fix:**

The saved state of OCXO and Rubidium frequency references is no longer lost when the clock is restarted. This ensures correct behaviour of the clock during the application of a firmware upgrade.

- **Bug Fix:**

SNMPv3 requests that fail authentication are now rejected when the maximum unauthenticated access is set to None.

- **Bug Fix:**

When acting as a PTP telecom slave, the clock will now resend subscription requests immediately after selecting a PTP telecom master if the running rate is faster than the discovery rate.

### VERSION 3.11r3 (Limited Release)

- **Improvement:**

Customer specific advanced configuration license added.

## VERSION 3.11r2 (9 January 2015)

- **Improvement:**  
Minor improvement to configuration communication protocol for compatibility with latest version of the configuration tool.

## VERSION 3.11r (1 October 2014)

- **Improvement:**  
Add the ability to configure ETH2 (when present) from ADMIN/ETH1 port.
- **Improvement:**  
Upgrade fault recovery improvements.
- **Improvement:**  
Add name of new sync source to "Sync source changed" syslog message.
- **Improvement:**  
Initial OCXO support.
- **Bug Fix:**  
Disable the test mode set time feature on ETH2 (when present). Test time is set by ADMIN/ETH1.
- **Bug Fix:**  
PTP Delay Asymmetry not stored to clock correctly.
- **Bug Fix:**  
Revert to factory settings not updating all settings.

## VERSION 3.10r (1 September 2014)

- **Improvement:**  
Add slave only PTP telecom profile.
- **Improvement:**  
Add ability to suppress power alarms.
- **Improvement:**  
Remove GPS related functions and alarms when acting as a fiber slave.
- **Improvement:**  
Increase range of the daylight savings change time to include 24:00.
- **Improvement:**  
Allow Block VLAN 0 to be set (But only via USB or a VLAN tagged Ethernet request).
- **Bug Fix:**  
IPv4 addresses with final octet > 233 were incorrectly rejected.
- **Bug Fix:**  
This bug caused occasional NTP multicast packets to be sent via broadcast.
- **Bug Fix:**  
Allow group creation in supervisor mode.

VERSION 3.08r (First release)