

OCXO & Rubidium

Oscillator Module Firmware Release Notes

VERSION F2.28r1 (October 2017)

- **Improvement:**
Added the ability to apply firmware upgrades to the GNSS receiver module of TCG 02-G clocks fitted with OCXO or Rubidium oscillators. This change allows for future field upgrades to be applied to the GNSS receiver module to add features or resolve issues.

VERSION 2.04f (10 August 2016)

- **Bug Fix:**
Fixed a bug that could cause the “No Antenna” alarm to clear intermittently on OCXO and Rubidium TCG 02-G clocks when the antenna is not connected.

VERSION 2.04d First Release (11 December 2015)